



# OpenFabrics Alliance

## Interoperability Logo Group (OFILG)

### February 2018 Logo Report



**UNH-IOL – 21 Madbury Rd., Suite 100 – Durham, NH 03824 – +1-603-862-0090**  
**OpenFabrics Interoperability Logo Group (OFILG) – ofalab@iol.unh.edu**

Tatyana Nikolova  
 Intel  
 1300 S. Mopac Expressway  
 Austin, TX 78746

Date: March 28, 2018  
 Report Revision: 1.0  
 OFED Version: OFED 4.8-2-rc3  
 OS Version: Scientific Linux 7.4

Enclosed are the results from OFA Logo testing performed on the following device under test (DUT):

*Intel X722 RNIC*

The test suite referenced in this report is available at the UNH-IOL website. Release 2.06-v3 (2017-12-6) was used.

<http://www.iol.unh.edu/ofatestplan>

The following table highlights the Mandatory test results required for the OpenFabrics Interoperability Logo for the DUT per the Test Plan referenced above and the current OpenFabrics Interoperability Logo Program (OFILP).

Test Procedures	IWG Test Status	Result/Notes
<a href="#">12.1: Ethernet Link Initialization</a>	Mandatory	Pass
<a href="#">13.4: TI uDAPL</a>	Mandatory	Pass
<a href="#">13.5: TI RDMA Basic Interoperability</a>	Mandatory	Pass
<a href="#">13.6: TI RDMA Stress</a>	Mandatory	Pass
<a href="#">13.7: TI MPI – Open MPI</a>	Mandatory	Pass

Summary of all results follows on the second page of this report.  
 For specific details regarding issues, please see the corresponding test result.

Testing Completed March 28, 2018 \_\_\_\_\_

Reviewed & Issued March 28, 2018

Adam LeBlanc  
[aleblanc@iol.unh.edu](mailto:aleblanc@iol.unh.edu)

\_\_\_\_\_

Stefan Oesterreich  
[soesterreich@iol.unh.edu](mailto:soesterreich@iol.unh.edu)

## Result Summary

The Following table summarizes all results from the event pertinent to this iWARP device class.

Test Procedures	IWG Test Status	Result/Notes
<a href="#">11.7 TI iSER</a>	Beta	Pass
<a href="#">12.1: Ethernet Link Initialization</a>	Mandatory	Pass
<a href="#">13.2 TI NFS over RDMA</a>	Beta	N/A
<a href="#">13.4: TI uDAPL</a>	Mandatory	Pass
<a href="#">13.5: TI RDMA Basic Interoperability</a>	Mandatory	Pass
<a href="#">13.6: TI RDMA Stress</a>	Mandatory	Pass
<a href="#">13.7: TI MPI – Open MPI</a>	Mandatory	Pass

### *Digital Signature Information*

This document was created using an Adobe digital signature. A digital signature helps to ensure the authenticity of the document, but only in this digital format. For information on how to verify this document's integrity proceed to the following site:

<http://www.iol.unh.edu/certifyDoc/>



If the document status still indicates "Validity of author NOT confirmed", then please contact the UNH-IOL to confirm the document's authenticity. To further validate the certificate integrity, Adobe 6.0 or later should report the following fingerprint information:

MD5 Fingerprint: 80 60 3C EA 42 D6 61 38 62 24 14 6A 1F 66 E9 84  
SHA-1 Fingerprint: 81 FF 90 E8 56 CB 95 7F 3E D6 4D B8 B2 99 EF BE 3C CC 7D DE

# Report Revision History

- v1.0 Initial working copy

## Configuration Files

Description	Attachment
Scientific Linux 7.4 Configuration File	
OFED 4.8-2-rc3 Configuration File	

## Result Key

The following table contains possible results and their meanings:

Result:	Description:
<b>PASS</b>	The Device Under Test (DUT) was observed to exhibit conformant behavior.
<b>PASS with Comments</b>	The DUT was observed to exhibit conformant behavior however an additional explanation of the situation is included.
<b>FAIL</b>	The DUT was observed to exhibit non-conformant behavior.
<b>Qualified PASS</b>	The DUT was observed to exhibit conformant behavior, with the exception of fault(s) or defect(s) which were previously known.
<b>Warning</b>	The DUT was observed to exhibit behavior that is not recommended.
<b>Informative</b>	Results are for informative purposes only and are not judged on a pass or fail basis.
<b>Refer to Comments</b>	From the observations, a valid pass or fail could not be determined. An additional explanation of the situation is included.
<b>Not Supported</b>	The DUT does not support the technology required to perform this test.
<b>Not Available</b>	Due to testing station limitations or time limitations, the tests could not be performed.
<b>Borderline</b>	The observed values of the specific parameters are valid at one extreme and invalid at the other.
<b>Not Tested</b>	Not tested due to the time constraints of the test period.


# DUT and Test Setup Information

The iWARP fabric configuration utilized for all testing is shown below.

February 2018  
iWARP Topology

Ethernet Addressing  
<hostname>.ofa

iWarp Addressing  
<hostname>-iw.ofa



DUT Details			
Manufacturer:	Intel	Firmware Revision:	0.2
Model:	X722	Hardware Revision:	0x0
Speed:	10Gb/s	Located in Host:	enceladus, erriapus
Additional Comments / Notes:			
To install the drivers for this device, linux kernel version > 4.8 must be installed prior to running install.pl for OFED-4.8-2-RC3			

## Mandatory Tests – IW Device Test Results:

### 12.1: Ethernet Link Initialization

<b>Test Result</b>	<b>Pass</b>
<b>Result Discussion:</b>	
All devices were shown to link and pass traffic to all other devices in a back-to-back configuration under nominal (unstressed) conditions.	

### 13.2: TI NFS over RDMA

Subnet Manager	Result
OpenSM	N/A
<b>Result Discussion:</b>	
NFSoverRDMA is not supported on SL7.4. Use SL7.3 if this functionality is needed.	

### 13.4: TI uDAPL

<b>Test Result</b>	<b>Pass</b>
<b>Discussion:</b>	
All devices were shown to communicate correctly using the Direct Access Programming Library, by use of the Linux daplttest tool.	

### 13.5: TI RDMA Basic Interoperability

<b>Test Result</b>	<b>Pass</b>
<b>Discussion:</b>	
All devices were shown to correctly exchange core RDMA operations across a simple network path under nominal (unstressed) conditions. Each HCA acted as both a client and a server for all tests.	

### 13.6: TI RDMA Stress

	Switch Load	Switch Fan In
<b>Test Result</b>	<b>Pass</b>	<b>Pass</b>
<b>Discussion:</b>		
All switches were seen to properly handle a large load as indicated by the successful completion of control communications between two RNICs while other RNICs in the fabric were used to generate traffic in order to put a high load on the switch.		

### 13.7: TI MPI – Open MPI

<b>Test Result</b>	<b>Pass</b>
<b>Discussion:</b>	
MPI Benchmarks were performed between all HCAs and were observed to exhibit the proper behavior.	