

# **OpenFabrics Alliance**

# **Interoperability Logo Group (OFILG)**



# July 2017 Logo Report

UNH-IOL – 21 Madbury Rd., Suite 100 – Durham, NH 03824 – +1-603-862-0090 OpenFabrics Interoperability Logo Group (OFILG) – ofalab@iol.unh.edu

Eddie WaiDate:August 29, 2017BroadcomReport Revision:1.05300 California Ave.OFED Version:OFED 4.8Irvine, CA 92617OS Version:Scientific Linux 7.3

Enclosed are the results from OFA Logo testing performed on the following devices under test (DUTs):

Broadcom P150p NetXtreme-E Single-port 40Gb/50Gb Ethernet PCIe Adapter

The test suite referenced in this report is available at the UNH-IOL website. Release 2.05-v2 (2017-03-22) was used.

## https://iol.unh.edu/ofatestplan

The following table highlights the Mandatory test results required for the OpenFabrics Interoperability Logo for the RoCE Network Adapter device class per the Test Plan referenced above and the current OpenFabrics Interoperability Logo Program (OFILP).

Test Procedures	IWG Test Status	Result/Notes
12.2: RoCE Link Initialization	Mandatory	Pass
12.4: IPoCE	Mandatory	Pass
13.4: TI uDAPL	Mandatory	Pass
13.5: TI RDMA Basic Interop	Mandatory	Pass
13.6: TI RDMA Stress	Mandatory	Pass
13.7: TI RSockets	Mandatory	Pass
13.8: TI MPI – Open MPI	Mandatory	Pass

For specific details regarding issues, please see the corresponding test result.

Testing Completed August 29, 2017	Reviewed & Issued September 5th, 2017
Stefan Oesterreich	
soesterreich@iol.unh.edu	Bob Noseworthy
Adam LeBlanc	<u>ren@iol.unh.edu</u>
aleblanc@iol.unh.edu	

# **Result Summary**

The Following table summarizes all results from the event pertinent to this RoCE device class (RCA).

Test Procedures	IWG Test Status	Result/Notes
12.2: RoCE Link Initialization	Mandatory	Pass
12.4: IPoCE	Mandatory	Pass
13.2: TI NFSoRDMA	Beta	Not Tested
13.4: TI uDAPL	Mandatory	Pass
13.5: TI RDMA Basic Interop	Mandatory	Pass
13.6: TI RDMA Stress	Mandatory	Pass
13.7: TI RSockets	Mandatory	Pass
13.8: TI MPI – Open MPI	Mandatory	Pass

# **Digital Signature Information**

This document was created using an Adobe digital signature. A digital signature helps to ensure the authenticity of the document, but only in this digital format. For information on how to verify this document's integrity proceed to the following site:

http://www.iol.unh.edu/certifyDoc/

If the document status still indicates "Validity of author NOT confirmed", then please contact the UNH-IOL to confirm the document's authenticity. To further validate the certificate integrity, Adobe 6.0 or later should report the following fingerprint information:

MD5 Fingerprint: 7B 9B 0C 40 55 27 86 C0 F7 4A A3 45 DB F9 40 6E SHA-1 Fingerprint: 03 59 97 71 28 ED 17 7F 1A 83 C5 D0 1D A8 2B 98 3E 2F 0F E7

# **Report Revision History**

v1.0 Initial Release

**Configuration Files** 

Description	Attachment
Scientific Linux 7.3 Configuration File	<b>9</b>
OFED 4.8 Configuration File	9


# **Result Key**

The following table contains possible results and their meanings:

Result:	Description:
PASS	The Device Under Test (DUT) was observed to exhibit conformant behavior.
PASS with	The DUT was observed to exhibit conformant behavior however an additional
Comments	explanation of the situation is included.
Qualified PASS	The DUT was observed to exhibit conformant behavior, with the exception of fault(s) or defect(s) which were previously known.
FAIL	The DUT was observed to exhibit non-conformant behavior.
Warning	The DUT was observed to exhibit behavior that is not recommended.
Informative	Results are for informative purposes only and are not judged on a pass or fail basis.
Refer to Comments	From the observations, a valid pass or fail could not be determined. An additional explanation of the situation is included.
Not Applicable	The DUT does not support the technology required to perform this test.
Not Available	Due to testing station limitations or time limitations, the tests could not be performed.
Borderline	The observed values of the specific parameters are valid at one extreme and invalid at
	the other.
Not Tested	Not tested due to the time constraints of the test period.

# **DUT and Test Setup Information**

Figure 1: The RoCE fabric configuration utilized for all testing is shown below.



<b>DUT Details</b>			
Manufacturer:	Broadcom	Firmware Revision:	20.06.01.05
Model:	BCM957414A4140	Hardware Revision:	BCM57414B1
Speed:	40/50Gb/s	Located in Host:	bergelmir
Additional Comments / Notes:			
DUT tested at 40Gb/s			
Drivers for this event were obtained via: <a href="https://github.com/Broadcom/linux_nxt_cert_ofed4.8">https://github.com/Broadcom/linux_nxt_cert_ofed4.8</a> .			

# **Mandatory Tests - RoCE Device Test Results:**

#### 12.2: RoCE Link Initialization

Test Result	Pass
Result Discussion:	
All devices were seen to link at proper speeds. All ICMP requests were sent and received properly.	

#### 12.4: IPoCE

Test Result	Pass
Result Discussion:	
All devices were seen to link at proper speeds. All ICMP requests were sent and received properly.	

### 13.2: TI NFSoRDMA

Test Result	Not Tested
Discussion:	
NFS over RDMA is not working with OFED 4.8.	

### 13.4: TI uDAPL

**Test Result** 

Test Result	Pass
Discussion:	
Discussion:	

With the use of the dapltest utility, devices exhibited simple send receive, verification, polling, scatter gather on a point-to-point topology. Devices were then connected to a switched topology and, with the use of the dapltest utility, tested on correct use of multiple threads, RDMA read and write operations, pipeline tests with RDMA write scatter gather list and RDMA read, and the multiple switches test.

### 13.5: TI RDMA Basic Interoperability

Discussion: All devices were shown to correctly exchange core RDMA operations across a simple network path under nominal (unstressed) conditions. Each HCA acted as both a client and a server for all tests listed

- below.
  - Small & Large RDMA Read
  - Small & Large RDMA Write
  - Small & Large RDMA Send
  - Small & Large RDMA Verify

**Pass** 

## OFA Logo Report - July 2017

DUT: Broadcom BCM957414A4140 NetXtreme-E Single-port 40Gb/50Gb Ethernet PCIe Adapter

## 13.6: TI RDMA Stress

Test Result Pass
Discussion:

All CE switches seem to properly handle a large load as indicated by the successful completion of control communications between two RCAs while all other RCAs in the fabric were used to generate traffic in order to put a high load on the switch. Each RCA acted as both a client and a server for the control connection.

### 13.7: TI RSockets

Test Result	Pass	
Discussion:		
Utilizing the rstream utility, all RCAs were able to successfully perform General, Asynchronous,		
Blocking, and Non-blocking procedures.		

### 13.8: TI MPI - Open MPI

Test Result	Pass
Discussion:	
Intel MPI Benchmarks were performed between all RCAs and were observed to exhibit the successful	
behavior.	