



OpenFabrics Alliance

Interoperability Logo Group (OFILG)

February Logo Report



UNH-IOL – 21 Madbury Rd., Suite 100 – Durham, NH 03824 - +1-603-862-0090
OpenFabrics Interoperability Logo Group (OFILG) – ofalab@iol.unh.edu

Martin Schlining
DDN
8320-D Guilford Road
Columbia, MD 21046

Date: March 28, 2018
Report Revision: 1.0
OFED Version: 4.8-2-rc3
OS Version: Scientific Linux 7.4

Enclosed are the results from OFA Logo testing performed on the following devices under test (DUTs):

SFA7700
SFA14000

The test suite referenced in this report is available at the UNH-IOL website. Release 2.06-v3 (2017-12-6) was used.

<http://iol.unh.edu/ofatestplan>

The following table highlights the Mandatory test required for the OpenFabrics Interoperability Logo for the InfiniBand HCA device class per the Test Plan and the current OpenFabrics Interoperability Logo Program (OFILP).

Summary of all results follows on the second page of this report.

| Test Procedures | IWG Test Status | Result/Notes |
|---|-----------------|--------------|
| <u>11.1: Link Initialization</u> | Mandatory | PASS |
| <u>11.2: Fabric Initialization</u> | Mandatory | PASS |
| <u>11.5: SM Failover and Handover</u> | Mandatory | PASS |
| <u>11.6: SRP</u> | Mandatory | PASS |

For Specific details regarding issues, please see the corresponding test result.

Testing Completed March 28, 2018

Reviewed & Issued March 28, 2018

Adam LeBlanc
aleblanc@iol.unh.edu

Stefan Oesterreich
soesterreich@iol.unh.edu

Result Summary

The Following table summarizes all results from the event pertinent to this IB device class (InfiniBand HCA).

| Test Procedures | IWG Test Status | Result/Notes |
|---|-----------------|--------------|
| <u>11.1: Link Initialization</u> | Mandatory | PASS |
| <u>11.2: Fabric Initialization</u> | Mandatory | PASS |
| <u>11.5: SM Failover and Handover</u> | Mandatory | PASS |
| <u>11.6: SRP</u> | Mandatory | PASS |

Digital Signature Information

This document was created using an Adobe digital signature. A digital signature helps to ensure the authenticity of the document, but only in this digital format. For information on how to verify this document's integrity proceed to the following site:

<http://www.iol.unh.edu/certifyDoc/>

If the document status still indicates “Validity of author NOT confirmed”, then please contact the UNH-IOL to confirm the document’s authenticity. To further validate the certificate integrity, Adobe 6.0 or later should report the following fingerprint information:

MD5 Fingerprint: 80 60 3C EA 42 D6 61 38 62 24 14 6A 1F 66 E9 84

SHA-1 Fingerprint: 81 FF 90 E8 56 CB 95 7F 3E D6 4D B8 B2 99 EF BE 3C CC 7D DE

Report Revision History

- v1.0 Initial working copy

Configuration Files

| Description | Attachment |
|---|---|
| Scientific Linux 7.4 Configuration File |  |
| OFED 4.8-2-rc3 Configuration File |  |


Result Key

The following table contains possible results and their meanings:

| Result: | Description: |
|--------------------|---|
| PASS | The Device Under Test (DUT) was observed to exhibit conformant behavior. |
| PASS with Comments | The DUT was observed to exhibit conformant behavior however an additional explanation of the situation is included. |
| Qualified PASS | The DUT was observed to exhibit conformant behavior, with the exception of fault(s) or defect(s) which were previously known. |
| FAIL | The DUT was observed to exhibit non-conformant behavior. |
| Warning | The DUT was observed to exhibit behavior that is not recommended. |
| Informative | Results are for informative purposes only and are not judged on a pass or fail basis. |
| Refer to Comments | From the observations, a valid pass or fail could not be determined. An additional explanation of the situation is included. |
| Not Applicable | The DUT does not support the technology required to perform this test. |
| Not Available | Due to testing station limitations or time limitations, the tests could not be performed. |
| Borderline | The observed values of the specific parameters are valid at one extreme and invalid at the other. |
| Not Tested | Not tested due to the time constraints of the test period. |

DUT and Test Setup Information

The IB fabric configuration utilized is shown below.



OFA Logo Report – February 2018
DUT: SFA7700, SFA14000

| DUT #1 Details | | | |
|-------------------------------------|--------------------------------|--------------------|---------------|
| Manufacturer: | DDN | Firmware Revision: | 3.1.3.a.38832 |
| Model: | SFA7700 | Hardware Revision: | 0 |
| Speed: | FDR | Located in Host: | N/A |
| Firmware MD5sum: | d14326918f2ed0487732ee54c4101e | | |
| Additional Comments / Notes: | | | |

| DUT #2 Details | | | |
|-------------------------------------|--------------------------------|--------------------|---------------|
| Manufacturer: | DDN | Firmware Revision: | 3.1.3.a.38832 |
| Model: | SFA14000 | Hardware Revision: | 0 |
| Speed: | EDR | Located in Host: | N/A |
| Firmware MD5sum: | d14326918f2ed0487732ee54c4101e | | |
| Additional Comments / Notes: | | | |
| | | | |

Mandatory Tests – IB Device Test Results:

11.1: Link Initialization

| Results | Result |
|---|--------|
| Part #1: | PASS |
| Discussion: | |
| All links established with the DUT were of the proper link speed and width. | |

11.2: Fabric Initialization

| Subnet Manager | Result |
|--|--------|
| OpenSM | PASS |
| Result Discussion: | |
| All subnet managers used while testing with OFED 4.8 were able to correctly configure the selected topology. | |

11.5: SM Failover and Handover

| SM Pairings | Result |
|---|--------|
| OpenSM | PASS |
| Result Discussion: | |
| OpenSM was able to properly handle SM priority and state rules. | |

11.6: SRP

| Subnet Manager | Result |
|--|--------|
| OpenSM | PASS |
| Result Discussion: | |
| Communications between all HCAs and all SRP targets succeeded while OpenSM was in control of the fabric. | |