

UNH-IOL – 121 Technology Drive, Suite 2 – Durham, NH 03824 – +1-603-862-0090 OpenFabrics Interoperability Logo Group (OFILG) – ofalab@iol.unh.edu

Martin SchliningDate:31 August 2015DataDirect NetworksReport Revision:1.08320 Guilford Road Suite DOFED Version on Compute Nodes:3.18Columbia, MD 21046-2833Operating System on Compute Nodes:Scientific Linux 7.0

Enclosed are the results from OFA Logo testing performed on the following devices under test (DUTs):

DataDirect Networks SFA7700

DataDirect Networks SFA10K

DataDirect Networks SFA12K

The test suite referenced in this report is available at the UNH-IOL website. Release 2.04 (2015-Jul-23) was used.

#### http://iol.unh.edu/ofatestplan

The following table highlights the Mandatory test results required for the OpenFabrics Interoperability Logo for the SRP Target over InfiniBand device class per the Test Plan referenced above and the current OpenFabrics Interoperability Logo Program (OFILP).

Test Procedures	IWG Test Status	Result/Notes
11.1: Link Initialization	Mandatory	PASS
11.2: Fabric Initialization	Mandatory	PASS
11.5: SM Failover and Handover	Mandatory	PASS
11.6: SRP	Mandatory	PASS

Summary of all results follows on the second page of this report. For Specific details regarding issues, please see the corresponding test result.

Testing Completed August 31, 2015

Reviewed & Issued October 2, 2015

for Nours the

Stefan Oesterreich soesterreich@iol.unh.edu

Bob Noseworthy ren@iol.unh.edu

### **Result Summary**

The Following table summarizes all results from the event pertinent to this IB device class (SRP Target over InfiniBand).

Test Procedures	IWG Test Status	Result/Notes
11.1: Link Initialization	Mandatory	PASS
11.2: Fabric Initialization	Mandatory	PASS
11.5: SM Failover and Handover	Mandatory	PASS
11.6: SRP	Mandatory	PASS

### **Digital Signature Information**

This document was signed using an Adobe Digital Signature. A digital signature helps to ensure the authenticity of the document, but only in this digital format. For information on how to verify this document's integrity proceed to the following site:

#### http://www.iol.unh.edu/certifyDoc/

If the document status still indicated "Validity of author NOT confirmed", then please contact the UNH-IOL to confirm the document's authenticity. To further validate the certificate integrity, Adobe 9.0 should report the following fingerprint information:

MD5 Fingerprint: FF 91 7B BD 2E 1A 0E 24 16 A8 23 28 13 69 D0 72 SHA-1 Fingerprint: 0C 88 5A 63 08 51 9B E0 D1 96 59 62 5E B3 52 01 58 C9 AF 27

### **Report Revision History**

• v1.0 Initial working copy

## **Configuration Files**

Description	Attachment
Scientific Linux 7.0 Configuration File	9
OFED 3.18 Configuration File	9

**UNH-IOL** Report Revision: 1.0

### OFA Logo Event Report – July 2015

DUTs: DataDirect Networks SFA7700; DataDirect Networks SFA10K; DataDirect Networks SFA12K


# **Result Key**

The following table contains possible results and their meanings:

Result:	Description:
PASS	The Device Under Test (DUT) was observed to exhibit conformant behavior.
PASS with	The DUT was observed to exhibit conformant behavior however an additional
Comments	explanation of the situation is included.
Qualified PASS	The DUT was observed to exhibit conformant behavior, with the exception of fault(s) or defect(s) which were previously known.
FAIL	The DUT was observed to exhibit non-conformant behavior.
Warning	The DUT was observed to exhibit behavior that is not recommended.
Informative	Results are for informative purposes only and are not judged on a pass or fail basis.
Refer to Comments	From the observations, a valid pass or fail could not be determined. An additional explanation of the situation is included.
Not Applicable	The DUT does not support the technology required to perform this test.
Not Available	Due to testing station limitations or time limitations, the tests could not be performed.
Borderline	The observed values of the specific parameters are valid at one extreme and invalid at
	the other.
Not Tested	Not tested due to the time constraints of the test period.

### **DUT and Test Setup Information**

Figure 1: The IB fabric configuration utilized for any tests requiring a multi-switch configuration is shown below.



DUT #1 Details			
Manufacturer:	DataDirect Networks	Firmware Revision:	2.2.6
Model:	SFA10K	Hardware Revision:	N/A
Speed:	QDR	Located in Host:	N/A
Firmware MD5sum:	N/A		
Additional Comments / Notes:			

DUT #2 Details			
Manufacturer:	DataDirect Networks	Firmware Revision:	2.3.1.2.24801
Model:	SFA12K	Hardware Revision:	N/A
Speed:	FDR	Located in Host:	N/A
Firmware MD5sum:	N/A		
Additional Comments / Notes:			

## DUTs: DataDirect Networks SFA7700; DataDirect Networks SFA10K; DataDirect Networks SFA12K

<b>DUT #3 Details</b>			
Manufacturer:	DataDirect Networks	Firmware Revision:	2.3.1.2.24801
Model:	SFA7700	Hardware Revision:	N/A
Speed:	FDR	Located in Host:	N/A
Firmware MD5sum:	N/A		
Additional Comments / Notes:			

# **Mandatory Tests - IB Device Test Results:**

#### 11.1: Link Initialization

Results	
Part #1:	PASS
Discussion:	
All links established with the DUT were of the proper link speed and width.	

Link Partner		SFA10K	SFA7700	SFA12K
Intel 12200 (Switch)	) – QDR	PASS	PASS	PASS
Mellanox SX6025 (S	witch) – FDR	PASS	PASS	PASS
Mellanox SX6036 (S	witch) – FDR	PASS	PASS	PASS
Mellanox IS-5030 (S	Switch) – QDR	PASS	PASS	PASS
Mellanox SX6036G	(Switch) – FDR	PASS	PASS	PASS
DataDirect Network	ks SFA12K (SRP Target) – FDR	NA	NA	NA
DataDirect Network	DataDirect Networks SFA10K (SRP Target) – QDR		NA	NA
DataDirect Networks SFA7700 (SRP Target) – FDR		NA	NA	NA
NetApp Soyuz (SRP Target) – QDR		NA	NA	NA
NetApp Pikes Peak	(SRP Target) – QDR	NA	NA	NA
Host: hati	HCA: MCX354A-FCBT (FDR)	PASS	PASS	PASS
Host: titan	HCA: MCX354A-FCCT (FDR)	PASS	PASS	PASS
Host: phoebe	HCA: MCB194A-FCAT (FDR)	PASS	PASS	PASS
Host: pandora	HCA: MCB192A-FCAT (FDR)	PASS	PASS	PASS
Host: pan	HCA: QLE7342 (QDR)	PASS	PASS	PASS
Host: daphnis	HCA: QLE7340 (QDR)	PASS	PASS	PASS

#### 11.2: Fabric Initialization

Subnet Manager	Result	
OpenSM	PASS	
Result Discussion:		
All subnet managers used while testing with OFED 3.18 were able to correctly configure the selected topology.		

### OFA Logo Event Report – July 2015

DUTs: DataDirect Networks SFA7700; DataDirect Networks SFA10K; DataDirect Networks SFA12K

#### 11.5: SM Failover and Handover

SM Pairings	Result
OpenSM	PASS
Result Discussion:	
OpenSM was able to properly handle SM priority and state rules.	

#### 11.6: SRP

11.0.510		
Subnet Manager	Result	
OpenSM	PASS	
Result Discussion:		
Core and extended SRP communications between all HCAs and all SRP targets succeeded while OpenSM was in control of the fabric.		