



OpenFabrics Alliance

Interoperability Logo Group (OFILG)

May 2012 Logo Event Report

UNH-IOL – 121 Technology Drive, Suite 2 – Durham, NH 03824 - +1-603-862-0090

OpenFabrics Interoperability Logo Group (OFILG) – ofalab@iol.unh.edu

Martin Schlining
DataDirect Networks
8320 Guilford Road
Columbia, MD 21046

Date: 3 July 2012
Report Revision: 1.0
OFED Version on Compute Nodes: 1.5.4.1
Operating System on Compute Nodes: SL 6.2

Enclosed are the results from OFA Logo testing performed on the following devices under test (DUTs):

DataDirect Networks SFA12000

DataDirect Networks SFA10000

The test suite referenced in this report is available at the IOI website. Release 1.42 (2012-Apr-03) was used.

www.iol.unh.edu/services/testing/ofa/testsuites/OFA-IWG_Interoperability_Test_Plan-v1.42.pdf

The following table highlights the Mandatory test results required for the OpenFabrics Interoperability Logo for the DUT per the Test Plan referenced above and the current OpenFabrics Interoperability Logo Program (OFILP).

Additional beta testing than reflected in this report was performed using the DUT. A separate report will outline those results.

Test Procedures	IWG Test Status	Result/Notes
<u>10.1: Link Initialization</u>	Mandatory	PASS
<u>10.2: Fabric Initialization</u>	Mandatory	PASS
<u>10.5: SM Failover and Handover</u>	Mandatory	PASS
<u>10.6: SRP</u>	Mandatory	PASS

Summary of all results follows on the second page of this report.

For Specific details regarding issues, please see the corresponding test result.

Testing Completed 05 June 2012

A handwritten signature in blue ink that reads "Edward L. Mossman".

Edward L. Mossman
emossman@iol.unh.edu



Review Completed 03 July 2012

A handwritten signature in blue ink that reads "Bob Noseworthy".

Bob Noseworthy
ren@iol.unh.edu

Result Summary

The Following table summarizes all results from the event pertinent to this IB device class.

Test Procedures	IWG Test Status	Result/Notes
<u>10.1: Link Initialization</u>	Mandatory	PASS
<u>10.2: Fabric Initialization</u>	Mandatory	PASS
<u>10.5: SM Failover and Handover</u>	Mandatory	PASS
<u>10.6: SRP</u>	Mandatory	PASS

Digital Signature Information

This document was signed using an Adobe Digital Signature. A digital signature helps to ensure the authenticity of the document, but only in this digital format. For information on how to verify this document's integrity proceed to the following site:

http://www.iol.unh.edu/certifyDoc/certificates_and_fingerprints.php

If the document status still indicated “Validity of author NOT confirmed”, then please contact the UNH-IOL to confirm the document’s authenticity. To further validate the certificate integrity, Adobe 9.0 should report the following fingerprint information:

MD5 Fingerprint: B4 7E 04 FE E8 37 D4 D2 1A EA 93 7E 00 36 11 F3

SHA-1 Fingerprint: 50 E2 CB 10 21 32 33 56 4A FC 10 4F AD 24 6D B3 05 22 7C C0

Report Revision History

- v1.0 Initial working copy

Configuration Files

Description	Attachment
Scientific Linux 6.2 Configuration File	
OFED 1.5.4.1 Configuration File	


Result Key

The following table contains possible results and their meanings:

Result:	Description:
PASS	The Device Under Test (DUT) was observed to exhibit conformant behavior.
PASS with Comments	The DUT was observed to exhibit conformant behavior however an additional explanation of the situation is included.
FAIL	The DUT was observed to exhibit non-conformant behavior.
Warning	The DUT was observed to exhibit behavior that is not recommended.
Informative	Results are for informative purposes only and are not judged on a pass or fail basis.
Refer to Comments	From the observations, a valid pass or fail could not be determined. An additional explanation of the situation is included.
Not Applicable	The DUT does not support the technology required to perform this test.
Not Available	Due to testing station limitations or time limitations, the tests could not be performed.
Borderline	The observed values of the specific parameters are valid at one extreme and invalid at the other.
Not Tested	Not tested due to the time constraints of the test period.

DUT and Test Setup Information

Figure 1: The IB fabric configuration utilized for any tests requiring a multi-switch configuration is shown below.



DUT #1 Details

Manufacturer:	DataDirect Networks	Firmware Revision:	1.5.0.1-9876
Model:	SFA10000	Hardware Revision:	NA
Speed:	QDR	Located in Host:	NA
Firmware MD5sum:	c08a31922afc6692cc97868b17397ebc		

Additional Comments / Notes:

DUT #2 Details

Manufacturer:	DataDirect Networks	Firmware Revision:	1.5.0.1-9562
Model:	SFA12000	Hardware Revision:	NA
Speed:	FDR	Located in Host:	NA
Firmware MD5sum:			

Additional Comments / Notes:

Mandatory Tests – IB Device Test Results:

10.1: Link Initialization

Results	
Part #1:	PASS
Discussion:	
All links established with the DUT were of the proper link speed and width.	

Link Partner	SFA10000	SFA12000
Intel 12200 (Switch) – QDR	PASS	PASS
Mellanox SX6025 (Switch) – FDR	PASS	PASS
Mellanox SX6036 (Switch) – FDR	PASS	PASS
Mellanox IS-5030 (Switch) – QDR	PASS	PASS
DataDirect Networks SFA12000 (SRP Target) – FDR	NA	NA
DataDirect Networks SFA10000 (SRP Target) – QDR	NA	NA
DataDirect Networks S2A9900 (SRP Target) – DDR	NA	NA
LSI Pikes Peak (SRP Target) – QDR	NA	NA
LSI XBB2 (SRP Target) – DDR	NA	NA
Mellanox BX5020 (Gateway) - QDR	PASS	PASS
Host: Themis	HCA: MHQH29C-XTR (QDR)	PASS
Host: Pan	HCA: MHQH19B-XTR (QDR)	PASS
Host: Hati	HCA: MCX353A-FCBT (FDR)	PASS
Host: Titan	HCA: MCX354A-FCBT (FDR)	PASS

10.2: Fabric Initialization

Subnet Manager				
OpenSM	IS-5030 SM	SX-6036 SM	12200 SM	WinOF SM
PASS	PASS	PASS	PASS	PASS
Result Discussion:				
All subnet managers used while testing with OFED 1.5.4.1 were able to correctly configure the selected topology.				

10.5: SM Failover and Handover

SM Pairings		Result
OpenSM OFED 1.5.4.1	OpenSM OFED 1.5.4.1	PASS
Result Discussion:		
OpenSM was able to properly handle SM priority and state rules.		

10.6: SRP

Subnet Manager				
OpenSM	IS-5030 SM	SX-6036 SM	12200 SM	WinOF SM
PASS	PASS	PASS	PASS	PASS
Result Discussion:				
SRP communications between all HCAs and all SRP targets succeeded while the above mentioned SMs were in control of the fabric.				