UNH-IOL – 121 Technology Drive, Suite 2 – Durham, NH 03824 – +1-603-862-0090 OpenFabrics Interoperability Logo Group (OFILG) – ofalab@iol.unh.edu

Troy Leedberg Date: February 24, 2014
Chelsio Communications Report Revision: 1.1
370 San Aleso Avenue #100 OFED Version: 3.5-2
Sunnyvale, CA 94085 OS Version: Scientific Linux 6.4

Enclosed are the results from OFA Logo testing performed on the following devices under test (DUTs):

Chelsio Communications T420-CR RNIC Chelsio Communications T420-CX RNIC

The test suite referenced in this report is available at the IOL website. Release 1.49 (2013-Nov-05) was used.

http://www.iol.unh.edu/ofatestplan

The following table highlights the Mandatory test results required for the OpenFabrics Interoperability Logo for the DUT per the Test Plan referenced above and the current OpenFabrics Interoperability Logo Program (OFILP).

Test Procedures	IWG Test Status	Result/Notes
	Mandatory	PASS
12.1: Ethernet Link Initialization		
13.1: TI iSER	Beta	Not Available
13.2: TI NFS over RDMA	Beta	Not Available
13.4: TI uDAPL	Mandatory	PASS
13.5: TI RDMA Basic Interoperability	Mandatory	PASS with Comments
13.6: TI RDMA Stress	Mandatory	PASS
<u>13.7: Ti MPI – Open</u>	Mandatory	PASS

Summary of all results follows on the second page of this report. For specific details regarding issues, please see the corresponding test result.

Testing Completed January 28, 2014	Review Completed February 24, 2014
C Polings	Pl mesanen
Charles Valenza	Edward Mossman
cvalenza@iol.unh.edu	emossman@iol.unh.edu

Result Summary

The Following table summarizes all results from the event pertinent to this iWARP device class.

Test Procedures	IWG Test Status	Result/Notes
12.1: Ethernet Link Initialization	Mandatory	PASS
13.1: TI iSER	Beta	Not Available
13.2: TI NFS over RDMA	Beta	Not Available
13.4: TI uDAPL	Mandatory	PASS
13.5: TI RDMA Basic Interoperability	Mandatory	PASS with Comments
13.6 TI RDMA Stress	Mandatory	PASS
13.7: TI MPI – Open	Mandatory	PASS

Digital Signature Information

This document was created using an Adobe digital signature. A digital signature helps to ensure the authenticity of the document, but only in this digital format. For information on how to verify this document's integrity proceed to the following site:

http://www.iol.unh.edu/certifyDoc/

If the document status still indicates "Validity of author NOT confirmed", then please contact the UNH-IOL to confirm the document's authenticity. To further validate the certificate integrity, Adobe 6.0 or later should report the following fingerprint information:

MD5 Fingerprint: 41 1E 00 9F 79 4D 02 EF E6 95 65 57 A4 71 4F 9F SHA-1 Fingerprint: 44 51 9E 22 66 59 1A D3 A1 F9 0B EE BD 01 90 80 BE 61 A4 A8

Report Revision History

- v1.0 Initial Release
- v1.1 Modified test 13.6 to more accurately reflect the behavior of the DUT

Configuration Files

Description	Attachment
Scientific Linux 6.4 Configuration File	9
OFED 3.5-2 Configuration File	Q


Result Key

The following table contains possible results and their meanings:

Result:	Description:
PASS	The Device Under Test (DUT) was observed to exhibit conformant behavior.
PASS with	The DUT was observed to exhibit conformant behavior however an additional
Comments	explanation of the situation is included.
Qualified PASS	The DUT was observed to exhibit conformant behavior, with the exception of fault(s) or
	defect(s) which were previously known.
FAIL	The DUT was observed to exhibit non-conformant behavior.
Warning	The DUT was observed to exhibit behavior that is not recommended.
Informative	Results are for informative purposes only and are not judged on a pass or fail basis.
Refer to Comments	From the observations, a valid pass or fail could not be determined. An additional
	explanation of the situation is included.
Not Applicable	The DUT does not support the technology required to perform this test.
Not Available	Due to testing station limitations or time limitations, the tests could not be performed.
Borderline	The observed values of the specific parameters are valid at one extreme and invalid at
	the other.
Not Tested	Not tested due to the time constraints of the test period.

DUT and Test Setup Information

The IW fabric configuration utilized for all testing is shown below.



DUT #1 Details			
Manufacturer:	Chelsio	Firmware Revision:	0.262.512 (SFP+)
Model:	T420-CR	Hardware Revision:	Rev 01
Speed:	10Gb/s	Located in Host:	mimas, rhea
Additional Comments / N	lotes:		
SFP+ card			

DUT #2 Details			
Manufacturer:	Chelsio	Firmware Revision:	0.262.512 (CX4)
Model:	T420-CX	Hardware Revision:	Rev A
Speed:	10Gb/s	Located in Host:	hyperion, calypso
Additional Comments / Notes:			
CX4 card			

Mandatory Tests - IW Device Test Results:

12.1: Ethernet Link Initialization

Test Result	PASS	
Result Discussion:		
All devices were shown to link and pass traffic to all other devices in a back-to-back configuration under		
nominal (unstressed) conditions.		

Intel NE020 **Link Partner** RNIC: Chelsio T4 **PASS PASS** RNIC: Intel NE020 **PASS**

PASS

13.1: TI iSER

Test Result	Not Tested	
Result Discussion:		
There were no iSER targets available in the cluster, therefore this was not tested.		

13.2: TI NFS over RDMA

Test Result	Not Tested	
Result Discussion:		
This test is not required for logo certification due to its beta status.		

13.4: TI uDAPL

Test Result	PASS	
Discussion:		
All devices were shown to communicate correctly using DAPL, by use of the Linux dapltest tool.		

13.5: TI RDMA Basic Interoperability

Test Result	PASS with Comments	
Discussion:		
RDMA read and write operations were observed to perform successfully between all RNICs in the		
cluster. RDMA sends smaller than size 240 were observed to fail due to OFED bug 2457.		

13.6: TI RDMA Stress

	Switch Load	Switch Fan In	
Test Result	PASS	PASS	
Discussion:			
All switches were seen to properly handle a large load as indicated by the successful completion of			

All switches were seen to properly handle a large load as indicated by the successful completion of control communications between two RNICs while other RNICs in the fabric were used to generate traffic in order to put a high load on the switch.

13.7: TI MPI – Open MPI

Test Result	PASS	
Discussion:		
Complete heterogeneity; 1 process per system as described in the cluster topology.		